Linac Intensity Upgrade

V. LoDestro / D. Raparia November 13, 2012

2014 BLIP/RRPL Operations Review



OUTLINE

- Linac performance
- **Intensity Upgrade**
- RF Tubes, Strategy
- Present Status



Acknowledgements

J. Alessi, G. Atoian, B. Briscoe, F. Carlino, T. Flanagan, D. Gassner, P. Ingrassia, T. Lehn, V. Lodestro, G. Omar, D. Raparia, J. Ritter, W. Shaffer, A. Zelenski

Performance

Current LINAC Beam Parameters

Frequency

Injection Energy

Final Energy*

■ Peak H⁻ Current

Pulse Length

Repetition Rate

Number of Tanks

Length

Total Peak RF Power

201.25 MHz

0.750 MeV

10-200 MeV

 $42 \text{ mA/} \sim .5 \text{ mA P}^{\wedge}$

450 µs

6.67 Hz

9

144.8 m

22 MW




^{*}Energy can be changed pulse-to-pulse

Linac Modes of Operation

Mode	BLIP (%)	RHIC(%)
Dedicated	100	0
RHIC with P [^]	92.5	7.5
AGS Setup/Study Day and Evening	95	5
200 MeV P [^] setup/study Day and Evening	91.6	8.3

Historical Average Beam Current Delivered to BLIP





Brookhaven Science Associates U.S. Department of Energy



Intensity Upgrade Phase 1

Upgrade - Phase I

- Increase beam current by 15%. 5% through ion source and Low Energy Beam Transport / Medium Energy Transport improvements. 10% through RF flattop increases and beam triggering.
- Evaluate the proposal to double the Linac beam current
 - Evaluate and prototype quadrupole pulse modulators flattops for 900 µs beam
 - Evaluate conditions of water cooling channels in drift tubes and accelerator cavities
 - Prototype RF system for 1100 µs pulse length
 - Recommend Phase 2 requirements for 240 µA average linac beam current.
- Completion FY-2016 operations

Doubling the Linac Current

(after 2016)


■ Note design Duty Cycle for the Linac RF is 0.4%, for Beam 0.2%

	Present	Phase 1	Phase 2
Peak Beam current	42 mA	45 mA	45 mA
Max Avg Beam current	120 μΑ	140 μΑ	240 μΑ
Beam Pulse Length	450 μs	480 μs	900 µs
RF Pulse Length	650 µs	670 μs	1100 µs
RF Duty Cycle	0.43%	0.44%	0.73%
Rep. Rate	6.67 Hz	6.67 Hz	6.67 Hz

Coax and Phase Shifter

Linac 12" Coax Transmission Line PA to Accelerator

LoDestro, Shaffer, Briscoe



U-Bend



Brookhaven Science Associates U.S. Department of Energy



RF Rise Time Measurements


LoDestro, Briscoe

Tank #	Rise time (90%, µs)	Beam delay (µs)
1	53.1	127.33
2	48.88	127.10
3	48.6	125.10
4	50.0	126.88
5	51.7	127.77
6	52.0	127.70
7	54.89	130.00
8	60.0	106.22
9	61.0	127.10



RF Rise Time Measurements

LoDestro, Briscoe





Tank3: Rise time (90%) 48.7 μs Beam delay 125.1 μs

Tank8: Rise time (90%) 60.4 μs Beam delay 106.22 μs

Phase Measurement Test Set up





Job Plan:

fill

Remove u-bend and straight sections Measure phase shift of removed pieces Install 3 1/8" phase shifter at same phase

Operate RF System at 600 kW, adjust phase shifter for minimum linac cavity

time

Reinstall u-bend with corrected phase straight sections


Brookhaven Science Associates U.S. Department of Energy



Results of rise time measurement to date at 2.79 MW cavity power

TK-8 Rise time $64 \mu s + 10 \text{ deg legs}$


TK-8 Rise time 68 µs orig legs / over +10 deg legs





Results of rise time measurement to date at 2.79 MW cavity power

- Best response, -10 degree sections will be installed in each u-bend leg



Needed to evaluate the source operation with extended pulse width (duty factor)

Test stand completed with new vacuum pump and oscilloscope purchased New gas valve electronics prototyped New arc pulser FET switch developed Beam delivered to test box





Quad PS Test for Doubling the Pulse Length


250 Amps Peak Current

Lodestro, Briscoe


Existing quad pulsers can't handle the extended pulse width

Original specification 0.1% current regulation over 200 μs beam, =25 ma


Normal Pulser 570 μs FT ΔI 2A, 0.8%



Doubled Cap Bks 890 μs FT ΔI 2.5A, 1.0%




Doubled Cap Bks 1.08 ms FT ΔI 6.25A, 2.5%



Brookhaven Science Associates U.S. Department of Energy

MEBT Transistor Pulser Design, 1ms FT ΔI <0.5A, 0.2%



Water channel in tank and quad examination with borescope

- VideoScope was just received last week
- Working with vendor it was determined that the smallest industrial probe available, 2mm dia, would not be able to make the several 90 degree bends to get into a drift tube cooling passage. Tk1 drift tube 15 was attempted.
- We will continue the examination of cooling passages in drift tube stems and cavity cooling channels.





Linac Tubes, Goal Maintain Min 5 Yr inventory of ea tube type

LoDestro

Tube Type	Ave Failure/yr	Spares	~operating yrs	FY14 k\$/tube
ML8618 (modulator)	7	37	5.2	10.4 (rebuild)
LPT-32 (Amplitude Loop)	2.3	10	4.3	7.9 (rebuild)
4CW25000 (Grid)	1.8	12	6.6	2.3 (rebuild) 5.7(New)
4616V (driver)	4	13	3.25	48.2 (rebuild) 68.0 (new)
7835 V2 (PA)	3	16	5.3	136 (~rebuild) 248(new)
7651 (pre amplifier)	14.5	23	1.6	2.6 (new)

- This year's purchases not included in the inventory
 - 8618 10 ea. LPT-32 2ea., 4CW25000 1ea.
 - 7835 2 ea., 4616 2 ea., 7651 5 ea., (PO not yet dispatched)



Milestone Goals

On Schedule to meet our Dec 2014 Goals

3 Month Goals	Project Funded April 2014
09/2014	 Complete quad pulse flattop extension analysis Complete Complete specifications and submit web requisitions, all coax components and fabrication contract, Borascope, Source vacuum pump, energy storage capacitors, crowbar ignitrons Complete Work Plan coax modifications to U-Bends Complete
12/2014	 Rework Coax U-Bends in RF Modules 2 – 4 Borascope a sampling of tank drift tube and cavity cooling channels for erosion
03/2015	 Prepare simulated drift tube w/quad for temperature rise measurement Specify and order P.S. for Modulator and Driver extended duty test
06/2015	1. Modify RF Test Bay, 10 th System, for extended duty testing. System testing begins.
09/2015	 Complete Mod 10 RF system testing H- Source Test Stand completed, source testing begins for current increases
12/2015	 Install Coax U-Bends in RF Modules 6 – 9 complete Complete tank quad temperature rise measurement using Tank 1 cavity cooling station
06/2016	1. Linac tuned for 15% intensity increase.
09/2016	1. Prepare final report on project results and make recommendations for Phase II



Summary: Intensity Upgrade Phase I (AIP)

Work is on schedule and within planned cost

15% intensity increase:

- Test Stand ion source is operating, new gas valve PS is being tested, new vacuum pump is installed
- RF rise time for all 9 system has been measured
- Optimizing coax lengths to minimize rise time and beam delay is in process. We are meeting our milestone goals.

Evaluation of pulse length doubling:

- Present quadrupole PS will not support 900 µs pulse length. We have received engineering quote for new PS's based on our specification (~10k\$ each 50K NRE)
- Examinations for water channels in tanks and quad has started, expected to finish before run starts.



Back up slides



Phase Shifters

■ 12" Coax



3 1/8" Coax






Results of rise time measurement to date

- Moving the 12" phase shifter to replace each ubend was determined to be unworkable due to its size, rigging, and infrastructure changes to the facility since 1995 eliminating clear and safe working access to the job. Therefore we substituted the much smaller 3 1/8" shifter measuring at a lower power level but maintaining the system phase shifts through each operational component.
- Tank 8 was the first system to be selected due to its clear access to the ubend and slow rise time.

Rise Time 40 uSec Shifter out / in



Rise Time 64 uSec -14 Degrees





Results of rise time measurement to date

Rise time 60 uSec +25 Degrees



This Year's Performance

